



The
Professional's Choice
for **Environmental Testing**™

1675 North Commerce Parkway, Weston, Florida 33326
Tel: (954) 384-4446 Fax: (954) 384-4838


WESTBROOK HOMES LLC
2041 PINEHURST DR
GARDENDALE, AL 35071

CERTIFICATE OF BULK ASBESTOS ANALYSIS

Prepared for: WESTBROOK HOMES LLC
Phone Number:
Fax Number:
Email Address: westbrook.anthony@gmail.com
Test Location: 102
102 ALFO AVE
BIRMINGHAM, AL 35226
Report Number: 121516-0247
Date Sampled: Dec 13, 2016
Date Analyzed: Dec 15, 2016
Report Date: Dec 15, 2016

Andrew Pittman, QA/QC Manager

Analytical results and reports generated by PRO-LAB/SSPTM, Inc. are generated for and at the request of its client(s) named on this report, and for their exclusive use. PRO-LAB/SSPTM, Inc. does not release original, copies or verbal results to any third party without prior written approval from the named client(s). This report applies only to the sample(s) tested. This report must not be reproduced, except in full, without written approval from PRO-LAB/SSPTM, Inc. The client(s) is solely responsible for the use and interpretation of test results and reports requested from PRO-LAB/SSPTM, Inc. This report must not be used by the client to claim product endorsement by NVLAP, NIST or any other agency of the U.S. Government. PRO-LAB/SSPTM, Inc. is not able to assess the degree of hazard resulting from materials analyzed. PRO-LAB/SSPTM, Inc. reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise requested. Asbestos samples from New York are analyzed by Environmental Hazards Services, LLC, NY ELAP #11714.



If you have questions or comments, please contact PRO-LAB at (954) 384-4446



BULK ASBESTOS ANALYSIS

1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

PREPARED FOR
WESTBROOK HOMES LLC
2041 PINEHURST DR
GARDENDALE, AL 35071

CHAIN OF CUSTODY #: 1003074
TEST ID NUMBER: 121516-0247
SAMPLING DATE: Dec 13, 2016
DATE RECEIVED: Dec 15, 2016
DATE ANALYZED: Dec 15, 2016
REPORT DATE: Dec 15, 2016
SAMPLE LOCATION: ATTIC UNDER INSULATION
COLOR / DESCRIPTION: WHITE
SERIAL #

TEST LOCATION
102
102 ALFO AVE
BIRMINGHAM, AL 35226

SAMPLE LAYER: 1

All percentages are visually estimated by volume

ASBESTOS FIBERS

Chrysotile: 15%
Amosite: ND
Crocidolite: ND
Anthophyllite: ND
Tremolite: ND
Actinolite: ND

NON-FIBROUS MATERIALS

Vermiculite: ND
Biotite: ND
Mica: ND
Perlite: ND
Aggregates: ND
Styrofoam: ND

NON-ASBESTOS FIBERS


Synthetics: ND
Mineral Wool: ND
Fiberglass: ND
Cellulose: ND
Animal Hair: ND
Antigorite: ND


OTHERS

Aluminum: ND
Bitumen: ND
Resilient Material: ND
Glue: ND
Binders: 85%

COMMENTS:

Note: Limit of Quantification (LOQ) = 1%. 'Trace' indicates the presence of asbestos below the LOQ. 'ND'=None Detected.


Andrew Pittman, PLM Analyst


Andrew Pittman, QA/QC Manager



The EPA requirement for analyzing and reporting asbestos is as follows: A substance that contains less than 1% is not considered to have asbestos even though this may still contain traces of asbestos (just less than 1%). For further information please visit the EPA website at www.epa.gov/iaq/asbestos.html.

All analyses are performed in accordance with the EPA 600/M4-82-020 method. This report must not be reproduced except in full, without written approval from PRO-LAB/SSPTM, Inc. These test results apply only to the samples actually tested. Floor tile is non-homogeneous and results reflect sample content. All samples will be stored for a period of thirty (30) days. The refractive index was determined by using 'Rapidly and Accurately Determining Refractive Indices of Asbestos Fibers by Using Dispersion Staining Method', by S-C. Su. The information contained in this report and any attachments is confidential information intended only for the use of the individual or entities named above. This report must not be used by the client to claim product endorsement by NVLAP, NIST or any other agency of the U.S. Government.